

HISTORIC AMERICAN ENGINEERING RECORD

HAER-VA-1

Master Photo Caption List

Humpback Covered Bridge, Covington VA
Photos by Jack Boucher, 1963, 1971

- VA-1-1 General view of northeast portal.
- VA-1-2 General view of portal.
- VA-1-3 General view from west.
- VA-1-4 General view from east.
- VA-1-5 General view from east.
- VA-1-6 General view from southwest of east side.
- VA-1-7 View from northeast end, East side.
- VA-1-8 View looking north.
- VA-1-9 Detail underside view of bridge from southwest.
- VA-1-10 Detail view of bridges underside.
- VA-1-11 Detail view of northeast abutment from east.
- VA-1-12 General view of interior from SW.
- VA-1-13 General interior view.
- VA-1-14 General view of interior from southwest.
- VA-1-15 General interior view.
- VA-1-16 Detail view of interior truss.
- VA-1-17 Detail view of deck.
- VA-1-18 Detail view of deck.
- VA-1-19 Detail view of roof support structure.

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

ADDENDUM TO
HUMPBACK COVERED BRIDGE
Humpback Bridge Wayside Park, spanning Dunlap Creek
Covington Vicinity
Alleghany County
Virginia

HAER No. VA-1
(Page 2)

Photographs VA-1-1 to VA-1-19 were previously transmitted to the Library of Congress in the early 1970s.

INDEX TO BLACK & WHITE PHOTOGRAPHS

Jet Lowe, Photographer, 2002.

- VA-1-20 SOUTHEAST BY 150°, ELEVATION.
- VA-1-21 SOUTHWEST BY 230° FROM EAST BANK OF DUNLAP CREEK
- VA-1-22 INTERIOR TRUSS VIEW, NORTH PANEL, LOOKING WEST BY 290°.
- VA-1-23 ELEVATION, WESTERN PORTAL.
- VA-1-24 INTERIOR, LOOKING EAST AT PEGGED CONSTRUCTION.
- VA-1-25 CENTER POST DETAIL.

INDEX TO COLOR TRANSPARENCIES

All color xerographic copies were made from a duplicate color transparency.

Jet Lowe, Photographer, 2002.

- VA-1-26 (CT) SOUTHEAST BY 150°, ELEVATION.